

LEAD PAINT INSPECTION REPORT

DATE: 08/26/96
 INSPECTION FOR: BALL STATE UNIVERSITY APARTMENTS
 PERFORMED AT: SCHEIDLER AND ANTHONY APARTMENTS
 INSTRUMENT TYPE: MICROLEAD 1, PORTABLE X-RAY FLOURESCENCE,
 LEAD-BASED PAINT ANALYZER
 ACTION LEVEL: 1.0 mg/cm2
 REGISTRATION NO.: XRF-SN-C-9232

This report has been produced in accordance with accepted guidelines. The measurements contained within may or may not be accurate based on information we received about the equipment used after the measurements were taken. Please direct questions to the University Apartment Office at (765) 285-5095.

SIGNED : Janice Wilkins, R.E.H.S DATE: 10/25/96
 Del. Co. Health Dept.
 SIGNED : William L. Morgan R.E.H.S DATE: 10/29/96
 Ball State University

SUMMARY REPORT OF LEAD PAINT INSPECTION FOR:
 Ball State University Apartments

Inspection Date: 08/26/96
 Report Date: 10/24/96
 Abatement Level: 1.0
 Total Readings: 67 Actionable: 27
 Initial Cal. : 3.1

---Space Description---

Read No.	Structure	Location	Paint Cond.	Lead(mg/cm2)
3460 N. Tillotson				
001	Wall	Hall front entrance	s	0.5
002	Window	Front entrance	s	0.2
003	Wall	Recreation room, block wall	s	2.0
3708 N. Tillotson Apt #430				
004	Wall	Living room	s	0.8
005	Door	Front	s	0.2
006	Window	Living room, frame	s	0.6
007	Window	Living room, trim	s	0.6
008	Ceiling	Living room, ceiling beam	s	0.0
009	Wall	Upstairs Hall	s	0.7
010	Door	Bedroom door frame	s	1.1
3708 N. Tillotson Apt. # 433				
011	Door	Exterior storm door frame	s	0.4
012	Door	Entry door, wood	s	0.4
013	Door	Interior entry door frame	s	0.5
014	Wall	Living room	s	0.7
015	Wall	Upstairs Hallway	s	0.3
016	Door	Bedroom door frame	s	1.0
3700 N. Tillotson Apt. # 446				
017	Door	Exterior of front storm door	s	0.4
018	Door	Living room door frame	s	1.2
019	Wall	Bedroom #2	s	1.0
020	Door	Bedroom, door frame	s	1.5
3720 N. Tillotson Apt. # 450				
021	Wall	Living room	s	1.3
022	Door	Front door frame	s	1.5
3716 N. Tillotson Ave. # 410				
023	Wall	Living room	s	0.3
024	Door	Patio door frame	s	1.2
3712 N. Tillotson Apt. #417				
025	Wall	Living room	s	0.0
026	Door	Patio Door frame	s	0.6
027	Fence	Exterior wooden fence	s	0.8

3744 N. Tillotson Apt. # 400					
028	Door	Entry Door	s		0.0
029	Window	Exterior front window well	s		1.0
030	Wall	Living room	s		0.5
031	Fence	Exterior wooden fence	s		0.5
3736 N. Tillotson Apt. #364					
032	Wall	Living room	s		1.1
033	Wall	Bedroom, #2	s		1.2
034	Door	Bedroom closet door frame	s		0.0
3736 N. Tillotson Apt. #369					
035	Wall	Living room	s		1.2
3732 N. Tillotson Apt. #380					
036	Wall	Living room	s		0.6
037	Door	Living room door frame	s		1.4
038	Wall	Bedroom #1	s		1.3
039	Wall	Bedroom #2	s		0.2
3728 N. Tillotson Apt. #381					
040	Wall	Living room	s		1.1
3537 N. Tillotson Apt. #310					
041	Wall	Living room	s		0.8
3536 N. Tillotson Apt. #305					
042	Wall	Living room	s		0.7
3540 N. Tillotson Apt. #346					
043	Wall	Living room	s		0.9
3544 N. Tillotson Apt. #340					
044	Wall	Living room	s		0.3
2317 W. Bethel Apt. #8					
045	Door	Exterior front door frame	s		3.8
046	Wall	Living room	s		0.3
047	Door	Closet	s		0.6
048	Door	Bedroom door frame	s		0.1
2405 W. Bethel Apt. #14					
049	Door	Exterior front door frame	s		5.4
050	Wall	Living room	s		0.1
051	Door	Interior front door frame	s		0.1
052	Door	Front Door	s		1.4
2417 W. Bethel Apt. #18					
053	Door	Exterior front door frame	s		4.8
054	Wall	Living room	s		0.9
055	Wall	Bedroom #2	s		0.7
056	Window	Bedroom window frame	s		1.4
2413 W. Bethel Apt. #22					
057	Door	Exterior front door frame	s		4.4
058	Wall	Living room	s		1.3
Anthony Apt. Laundry Facility					
059	Wall	South wall	s		0.5
060	Window	Interior window frame	s		1.0
2301 W. Bethel Ave.					
061	Siding	Exterior brown wood siding	s		4.0
2301 W. Bethel Apt. #39					
062	Wall	Living room	s		0.7
2201 W. Bethel Apt. #63					
063	Wall	Living room	s		2.0
064	Door	Front	s		0.4
065	Wall	Exterior hall	s		0.8
2207 W. Bethel Apt. #87					
066	Wall	Living room	s		2.0
067	Door	Bedroom	s		0.6